

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-025685**Date Inspected:** 24-Jul-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** See below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Kelly Leavitt, was present during the times noted above for random observations relative to the work being performed.

Trial Assembly

This Quality Assurance Inspector (QA) performed Visual Testing (VT) review of randomly selected welds located on OBG14W that was previously tested by American Bridge Fluor (ABF) QA personnel using the Magnetic Particle (MT) and VT method. The following issue(s) have been noted and this QA Inspector provided a turnover to dayshift personal for tracking of these welds. The weld designations reviewed are as follows:

SP3140B-001-105,106,107,108

SP3141B-001-166,167,168,169,170,171,172,173,174,175,176,177,178,179

SP3142C-001-111,112,113,114,115,116,117,118,119,120,121,122,123,124

SP3143A-001-043,044,045,046,047,048,049,050,051,052,053,054,055,056

This QA inspector performed MT of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an MT report for this date. The member was identified as OBG 14W. The weld designations reviewed are as follows:

SP3142C-001-111,112,113,114,115,116

SP3141B-001-175,176,177,178,179

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Summary of Conversations:

“No relevant conversations.”

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Leavitt,Kelly	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer
